

User:
 Vehicle : C4 /C4
 VIN: VF7LANFUF74530400

Print date : 25 Август 2016 г. 21:26:34
 Start of vehicle session :
 Tool version : 07.02




Global test

/Global test

Family no.

Control unit

1



Built-in Systems Interface (BSI)

BSI

A4C9

Fault: illumination of the rear RH fog lamp.

Properties

From . Local .

Characterisation of the fault. Short circuit to positive.

6



Injection/ignition

ME745

P1536

Fault stop lamp information

Properties

Cause Distant

Status Intermittent

Characterisation of the fault Not characterised

List of associated variables

Engine speed 1940 rpm

Coolant temperature 107 °C

Vehicle speed 49 Kph

Measured manifold pressure 260.0 Mb/bit

Richness regulation status Open loop (special driving

conditions)

P0571

Vehicle cruise control fault/vehicle Speed Limitation

Properties

Cause Local

Status Intermittent

Characterisation of the fault Coherence

List of associated variables		
Engine speed	941	rpm
Coolant temperature	53	°C
Vehicle speed	0	Kph
Measured manifold pressure	520.0	Mb /bit
Richness regulation status	Open loop (conditions for switching to a closed loop not yet satisfied)	

P0591 Vehicle cruise control fault/vehicle Speed Limitation

Properties	
Cause	Local
Status	Intermittent
Characterisation of the fault	Coherence

List of associated variables		
Engine speed	941	rpm
Coolant temperature	53	°C
Vehicle speed	0	Kph
Measured manifold pressure	520.0	Mb /bit
Richness regulation status	Open loop (conditions for switching to a closed loop not yet satisfied)	

P0313 Misfiring fault : fuel level too low

Properties	
Cause	Distant
Status	Intermittent
Characterisation of the fault	Not characterised

List of associated variables		
Engine speed	829	rpm
Coolant temperature	42	°C
Vehicle speed	0	Kph
Measured manifold pressure	420.0	Mb /bit
Richness regulation status	Open loop (fault)	

U1003 Absence of communication on the CAN

Properties	
Cause	Distant
Status	Intermittent
Characterisation of the fault	Not characterised

List of associated variables		
Engine speed	0	rpm
Coolant temperature	108	°C
Vehicle speed	0	Kph
Measured manifold pressure	980.0	Mb /bit
Richness regulation status	Open loop (conditions for switching to a closed loop not yet satisfied)	

P0140 Fault downstream oxygen sensor signal

Properties	
Cause	Local
Status	Intermittent
Characterisation of the fault	Open circuit

List of associated variables		
Engine speed	2271	rpm
Coolant temperature	103	°C
Vehicle speed	21	Kph
Measured manifold pressure	450.0	Mb /bit
Richness regulation status	Closed loop	







ABS/traction control

ABS8_BOSCH

U1003 General CAN fault

Properties	
Cause	Distant
Status	Intermittent .
Characterisation of the fault	Not characterised

List of associated variables
Communication error

	gearbox	 ECU not recognised
	Power steering electric pump unit	GEP
	Engine relay unit	BSM















B998




















Fault: headlamp washer relay control

Properties

Characterisation of the fault. Short circuit to earth

Ownership not referenced Value not referenced

	Trailer relay unit	 BSR
	Driver and passenger airbags	SAC_AUTOLIV
	Multifunction display	EMF_A
	ECU at the top of the steering column	VCCF
	heating/ventilation	CLIM_RFTA
	Instrument panel	COMBINE
	Remote Instrument Panel Unit	COMPTE_TOURS
	Radio or radiotelephone (radio part)	AUTORADIO
	Anti-theft alarm	ALARME
	Passenger door electronics	EDPP
	Driver's door electronics	EDPC
	Automatic gearbox electric control	Not present
	Pneumatic suspension	Not present

	Diesel additive	Not present
	Diesel additive adding pump	Not present
	Under inflation detection	Not present
	Directional headlamps	Not present
	Battery charge status unit	Not present
	Electric secondary brake	Not present
	Lane departure warning system	Not present
	Windscreen wiper	Not present
	Parking aid	Not present
	audio amplifier	Not present
	CD player	Not present
	Telematics	Not present
	Hands-free kit (Telephone)	Not present
	Driver's seat memorizing unit	Not present
	Light pack unit	Not present
	Rain and brightness sensor	Not present
	Driving school module	Not present
	High frequency receiver	Not present
	Services module	Not present